ROHAN


niDiTA

D Wing

20241016

D Wing | 1st Floor

ROHAN NiDiTA



Area statement (sq.ft.)

Unit No.	Unit Type	Carpet Area	Balcony Area	Utility Area	Total Carpet Area
D - 101 (Guest Room)	1 BHK	NA	NA	NA	NA
D - 102	2 BHK	635.40	250.26	31.22	916.88
D - 103	2 BHK	635.40	250.26	31.22	916.88
D - 104	1 BHK	454.99	58.45	31.22	544.66
D - 105	2 BHK	639.49	237.24	31.22	907.94
D - 106	2 BHK	639.49	237.24	31.22	907.94



Disclaimer: The latest sanction plan for this project will hold true and supersede these sale plans. In the length of the project, due to any consultant inputs, or minor design alterations, following aspects may change: The beam locations, ledge walls inside the toilets / utility, all services shafts in common areas and plumbing shafts of toilets, along with maintenance slabs are indicative.

20241016

D Wing | 2nd Floor

ROHAN nIDITA



Area statement (sq.ft.)

Unit No.	Unit Type	Carpet Area	Balcony Area	Utility Area	Total Carpet Area
D - 201	1 BHK	459.41	55.76	31.22	546.38
D - 202	2 BHK	635.40	92.03	31.22	758.65
D - 203	2 BHK	635.40	92.03	31.22	758.65
D - 204	1 BHK	459.41	55.76	31.22	546.38
D - 205	2 BHK	635.40	92.03	31.22	758.65
D - 206	2 BHK	635.40	92.03	31.22	758.65



Disclaimer: The latest sanction plan for this project will hold true and supersede these sale plans. In the length of the project, due to any consultant inputs, or minor design alterations, following aspects may change: The beam locations, ledge walls inside the toilets / utility, all services shafts in common areas and plumbing shafts of toilets, along with maintenance slabs are indicative.

20241016

D Wing | 3rd Floor

ROHAN nIDITA



Area statement (sq.ft.)

Unit No.	Unit Type	Carpet Area	Balcony Area	Utility Area	Total Carpet Area
D - 301	2 BHK	635.40	160.38	31.22	827.0
D - 302	2 BHK	635.40	201.39	31.22	868.01
D - 303	2 BHK	635.40	201.39	31.22	868.01
D - 304	2 BHK	635.40	160.38	31.22	827.0
D - 305	2 BHK	635.40	194.61	31.22	861.23
D - 306	2 BHK	635.40	194.61	31.22	861.23



Disclaimer: The latest sanction plan for this project will hold true and supersede these sale plans. In the length of the project, due to any consultant inputs, or minor design alterations, following aspects may change: The beam locations, ledge walls inside the toilets / utility, all services shafts in common areas and plumbing shafts of toilets, along with maintenance slabs are indicative.

20241016

D Wing | 4th Floor

ROHAN
NiDiTA



Area statement (sq.ft.)

Unit No.	Unit Type	Carpet Area	Balcony Area	Utility Area	Total Carpet Area
D - 401	2 BHK	635.40	194.61	31.22	861.23
D - 402	2 BHK	635.40	194.61	31.22	861.23
D - 403	2 BHK	635.40	194.61	31.22	861.23
D - 404	2 BHK	635.40	194.61	31.22	861.23
D - 405	2 BHK	635.40	194.61	31.22	861.23
D - 406	2 BHK	635.40	194.61	31.22	861.23



Disclaimer: The latest sanction plan for this project will hold true and supersede these sale plans. In the length of the project, due to any consultant inputs, or minor design alterations, following aspects may change: The beam locations, ledge walls inside the toilets / utility, all services shafts in common areas and plumbing shafts of toilets, along with maintenance slabs are indicative.

20241016

D Wing | 5th, 6th, 8th, 13th, 18th, 19th & 20th Floor

ROHAN
nIDITA



Area statement (sq.ft.)

Unit No.	Unit Type	Carpet Area	Balcony Area	Utility Area	Total Carpet Area
D - 501, 601, 801, 1301, 1801, 1901, 2001	2 BHK	635.40	92.03	31.22	758.65
D - 502, 602, 802, 1302, 1802, 1902, 2002	2 BHK	635.40	92.03	31.22	758.65
D - 503, 603, 803, 1303, 1803, 1903, 2003	2 BHK	635.40	92.03	31.22	758.65
D - 504, 604, 804, 1304, 1804, 1904, 2004	2 BHK	635.40	92.03	31.22	758.65
D - 505, 605, 805, 1305, 1805, 1905, 2005	2 BHK	635.40	92.03	31.22	758.65
D - 506, 606, 806, 1306, 1806, 1906, 2006	2 BHK	635.40	92.03	31.22	758.65



Disclaimer: The latest sanction plan for this project will hold true and supersede these sale plans. In the length of the project, due to any consultant inputs, or minor design alterations, following aspects may change: The beam locations, ledge walls inside the toilets / utility, all services shafts in common areas and plumbing shafts of toilets, along with maintenance slabs are indicative.

20241016

D Wing | 7th, 12th & 17th Floor

ROHAN
NiDiTA



Area statement (sq.ft.)

Unit No.	Unit Type	Carpet Area	Balcony Area	Utility Area	Total Carpet Area
D - 701, 1201, 1701	2 BHK	635.40	92.03	31.22	758.65
D - 702, 1202, 1702	2 BHK	635.40	92.03	31.22	758.65
D - 703, 1203, 1703	1 BHK	455.10	60.17	31.22	546.49
D - 704, 1204, 1704	2 BHK	635.40	92.03	31.22	758.65
D - 705, 1205, 1705	2 BHK	635.40	92.03	31.22	758.65
D - 706, 1206, 1706	2 BHK	635.40	92.03	31.22	758.65



Disclaimer: The latest sanction plan for this project will hold true and supersede these sale plans. In the length of the project, due to any consultant inputs, or minor design alterations, following aspects may change: The beam locations, ledge walls inside the toilets / utility, all services shafts in common areas and plumbing shafts of toilets, along with maintenance slabs are indicative.

20241016

D Wing | 9th Floor

ROHAN NiDiTA



Area statement (sq.ft.)

Unit No.	Unit Type	Carpet Area	Balcony Area	Utility Area	Total Carpet Area
D - 901	2 BHK	635.40	92.03	31.22	758.65
D - 902	2 BHK	635.40	194.61	31.22	861.23
D - 903	2 BHK	635.40	92.03	31.22	758.65
D - 904	2 BHK	635.40	194.61	31.22	861.23
D - 905	2 BHK	635.40	92.03	31.22	758.65
D - 906	2 BHK	635.40	194.61	31.22	861.23




Disclaimer: The latest sanction plan for this project will hold true and supersede these sale plans. In the length of the project, due to any consultant inputs, or minor design alterations, following aspects may change: The beam locations, ledge walls inside the toilets / utility, all services shafts in common areas and plumbing shafts of toilets, along with maintenance slabs are indicative.

20241016

D Wing | 10th Floor

ROHAN NiDiTA



Area statement (sq.ft.)

Unit No.	Unit Type	Carpet Area	Balcony Area	Utility Area	Total Carpet Area
D - 1001	2 BHK	635.40	92.03	31.22	758.65
D - 1002	2 BHK	635.40	92.03	31.22	758.65
D - 1003	2 BHK	635.40	92.03	31.22	758.65
D - 1004	2 BHK	635.40	92.03	31.22	758.65
D - 1005	2 BHK	635.40	92.03	31.22	758.65
D - 1006	2 BHK	635.40	92.03	31.22	758.65



Disclaimer: The latest sanction plan for this project will hold true and supersede these sale plans. In the length of the project, due to any consultant inputs, or minor design alterations, following aspects may change: The beam locations, ledge walls inside the toilets / utility, all services shafts in common areas and plumbing shafts of toilets, along with maintenance slabs are indicative.

D Wing | 11th Floor

ROHAN
NiDiTA



Area statement (sq.ft.)

Unit No.	Unit Type	Carpet Area	Balcony Area	Utility Area	Total Carpet Area
D - 1101	2 BHK	635.40	92.03	31.22	758.65
D - 1102	2 BHK	635.40	194.61	31.22	861.23
D - 1103	2 BHK	635.40	92.03	31.22	758.65
D - 1104	2 BHK	635.40	194.61	31.22	861.23
D - 1105	2 BHK	635.40	92.03	31.22	758.65
D - 1106	2 BHK	635.40	194.61	31.22	861.23



Disclaimer: The latest sanction plan for this project will hold true and supersede these sale plans. In the length of the project, due to any consultant inputs, or minor design alterations, following aspects may change: The beam locations, ledge walls inside the toilets / utility, all services shafts in common areas and plumbing shafts of toilets, along with maintenance slabs are indicative.

20241016

D Wing | 14th Floor

ROHAN NiDiTA



Area statement (sq.ft.)


Unit No.	Unit Type	Carpet Area	Balcony Area	Utility Area	Total Carpet Area
D - 1401	2 BHK	635.40	194.61	31.22	861.23
D - 1402	2 BHK	635.40	92.03	31.22	758.65
D - 1403	2 BHK	635.40	194.61	31.22	861.23
D - 1404	2 BHK	635.40	92.03	31.22	758.65
D - 1405	2 BHK	635.40	194.61	31.22	861.23
D - 1406	2 BHK	635.40	92.03	31.22	758.65



Disclaimer: The latest sanction plan for this project will hold true and supersede these sale plans. In the length of the project, due to any consultant inputs, or minor design alterations, following aspects may change: The beam locations, ledge walls inside the toilets / utility, all services shafts in common areas and plumbing shafts of toilets, along with maintenance slabs are indicative.

D Wing | 15th Floor

ROHAN nIDITA





Area statement (sq.ft.)

Unit No.	Unit Type	Carpet Area	Balcony Area	Utility Area	Total Carpet Area
D - 1501	2 BHK	635.40	92.03	31.22	758.65
D - 1502	2 BHK	635.40	92.03	31.22	758.65
D - 1503	2 BHK	635.40	92.03	31.22	758.65
D - 1504	2 BHK	635.40	92.03	31.22	758.65
D - 1505	2 BHK	635.40	92.03	31.22	758.65
D - 1506	2 BHK	635.40	92.03	31.22	758.65

Disclaimer: The latest sanction plan for this project will hold true and supersede these sale plans. In the length of the project, due to any consultant inputs, or minor design alterations, following aspects may change: The beam locations, ledge walls inside the toilets / utility, all services shafts in common areas and plumbing shafts of toilets, along with maintenance slabs are indicative.

D Wing | 16th Floor

ROHAN NiDiTA



Area statement (sq.ft.)

Unit No.	Unit Type	Carpet Area	Balcony Area	Utility Area	Total Carpet Area
D - 1601	2 BHK	635.40	194.61	31.22	861.23
D - 1602	2 BHK	635.40	92.03	31.22	758.65
D - 1603	2 BHK	635.40	194.61	31.22	861.23
D - 1604	2 BHK	635.40	92.03	31.22	758.65
D - 1605	2 BHK	635.40	194.61	31.22	861.23
D - 1606	2 BHK	635.40	92.03	31.22	758.65



Disclaimer: The latest sanction plan for this project will hold true and supersede these sale plans. In the length of the project, due to any consultant inputs, or minor design alterations, following aspects may change: The beam locations, ledge walls inside the toilets / utility, all services shafts in common areas and plumbing shafts of toilets, along with maintenance slabs are indicative.

20241016

D Wing | 21st Floor

ROHAN
nIDITA



Area statement (sq.ft.)

Unit No.	Unit Type	Carpet Area	Balcony Area	Utility Area	Total Carpet Area
D - 2101	2 BHK	635.40	92.03	31.22	758.65
D - 2102	2 BHK	635.40	194.61	31.22	861.23
D - 2103	2 BHK	635.40	92.03	31.22	758.65
D - 2104	2 BHK	635.40	194.61	31.22	861.23
D - 2105	2 BHK	635.40	92.03	31.22	758.65
D - 2106	2 BHK	635.40	194.61	31.22	861.23



Disclaimer: The latest sanction plan for this project will hold true and supersede these sale plans. In the length of the project, due to any consultant inputs, or minor design alterations, following aspects may change: The beam locations, ledge walls inside the toilets / utility, all services shafts in common areas and plumbing shafts of toilets, along with maintenance slabs are indicative.

20241016